

TruDataSM Inspection Report

The TruDataSM Inspection Report mitigates risk and extends drill pipe lifecycle by identifying operational problems and improper care and handling. Knowing the true condition of your pipe helps ensure your pipe is fit-for-purpose for specific drilling applications

TruData is a comprehensive inspection reporting system for the classification, inspection, and repair of rotary shoulder drill stem components. The advanced reporting system provides a cradle to grave record of drill stem component inspections, connection repair, hardbanding, internal coating, and has the ability to provide trend analysis of maintenance, repairs and future replacement of drill stem components.

Application Management

The TruData reporting database houses all information, data, and results pertaining to plant and mobile inspections for the life of the pipe.


Upon completion of the inspection, preliminary reports are available to customers at the job site in an off-line status. Once the final inspection sheet is submitted by the inspector, multiple reports and trend analysis are readily available to internal users and customers.


System Highlights

- Detailed Reports
- Pipe Analysis
- Tool Joint Wear Data
- Recommended Repairs
- Historical Inspection Analysis

Available Reports

- Summary Report
- Tally Sheets
- IPC Coating Condition
- Machine Shop Report
- Field Repair Report
- Hardbanding Report
- Color Tally Report





Preliminary Field Report

Customer: TUBOSCOPE NOV WELLBORE TECHNOLOGIES	Size: 2 3/8"
WO #: 3659874	Weight: 6.65
P.O No.: 569874	Grade: E-75
Rig Name:	Connection: PAC
Well Name: Marker 17	

LENGTHS OVERVIEW

	Total
Lengths inspected:	10
Premium:	6
Class 2:	2
Class 3:	1
Reject:	1
Bent:	1
Lengths for immediate use:	7

MACHINE SHOP / CONNECTIONS

	Pin	Box	Repair Total	Pipe Total
Machine Reface (MRF):	1	1	2	1
Machine Recut (MRC):	0	0	0	0
Machine Hardband (MHB):	0	0	0	0
Bent pipe needs to be straightened:				0

FIELD REPAIR / CONNECTIONS

	Pin	Box	Repair Total	Pipe Total
Field Reface (FRF):	5	5	10	5
Hardband Repaired (HBR):	5	5	10	5
Bent pipe straightened during job:				0

**HARDBANDING REPAIRS
PREMIUM CLASS PIPE**

	Pin	Box	Total
Hardband Repaired (HBR):	1	1	2
Machine Hardband (MHB):	0	0	0
Okay:	0	0	0
None:	5	5	10

TOOL JOINT CLASS

	Pin	Box
Premium	9	9
Class 2	1	1
Reject	0	0

**HARDBANDING REPAIRS
CLASS 2 & 3 PIPE**

	Pin	Box	Total
Hardband Repaired (HBR):	3	3	6
Machine Hardband (MHB):	0	0	0
Okay	0	0	0
None:	0	0	0

COATING CONDITION

	Total
1 IPC	0
2 IPC	1
3 IPC	1
4 IPC	1
None	7

Inspection Date: Dec 24, 2013 - Jan 2, 2014

Sample Preliminary Field Report of TruDataSM

