


RELEASE NOTES

	Product	Version	Changes	Descriptions
	iGC	1.14	Improvements/Bug Fixes	<ul style="list-style-type: none"> This firmware release supports the upcoming iGC hardware revision 2.9 that was required due to some obsolete board components. IMPORTANT NOTE: The new 2.9 iGC board (hardware) revision will not be compatible with previous firmware versions. Therefore, you will not be able to downgrade the iGC firmware below version 1.14. The iSeries Firmware Updater software will determine which board is connected and will manage upgrade/ downgrade requests appropriately. Optimized the calculation for Vibration, defined as the RMS value of all acquired shock.
		1.13	Bug Fixes	<ul style="list-style-type: none"> Update to detect and correct memory logging issue (log pointer error).
		1.04	New Features/ Enhancements	<ul style="list-style-type: none"> Added high voltage feedback calibration. Added enhanced log extraction feature. Added unlock, lifetime odometer reset and serial/odometer reset commands. Reprogrammed re-write feature.