

Machining Services — North America, Canada, and Mexico

United States of America

Facility	State/Province	# of CNC Machines	Rotary Shoulder Connection	API 5B	Grant Prideco™ Licenses														Sub Manufacture	TTS (PH-6)			
					CTM™	Delta™	GPDS™	GT-M™	HT™	SST™	TTM™	TurboTorque™	TurboFrac-M™	uGPDS™	uXT™	wGPDS™	WTT™	wXT™			XTF™	XTM™	XT™
Kenai	Alaska	2 ML, 1 CNC	▲	▲																		▲	▲
North Slope	Alaska	3, 2 CNC Mill and 1 ML	▲	▲		▲	▲		▲													▲	▲
Bakersfield	California	2	▲						▲													▲	▲
Brighton	Colorado	2	▲			▲			▲													▲	▲
New Iberia*	Louisiana	10	▲		▲	▲	▲	▲	▲	▲	▲	▲	▲									▲	▲
Aztec	New Mexico	2	▲			▲		▲	▲				▲									▲	▲
Williston	North Dakota	3	▲			▲	▲		▲					▲						▲		▲	▲
Oklahoma City*	Oklahoma	8, 1 CNC Mill and 2 ML	▲		▲	▲	▲		▲	▲				▲	▲	▲						▲	▲
Corpus Christi*	Texas	3	▲		▲	▲	▲		▲	▲				▲	▲							▲	▲
Odessa	Texas	5 and 1 ML	▲			▲	▲		▲	▲				▲	▲							▲	▲
Pearland*	Texas	4	▲		▲		▲	▲	▲	▲				▲	▲							▲	▲
Kilgore	Texas	2	▲			▲	▲							▲	▲							▲	▲
Bridgeport	West Virginia	3	▲			▲	▲		▲	▲												▲	▲
Casper	Wyoming (YS)	1 ML	▲																			▲	▲
Casper	Wyoming (WPT)	4 and 1 ML	▲			▲	▲		▲	▲				▲								▲	▲
Sheldon South†‡	Houston	5		▲																			

Canada

Grande Prairie	Alberta	1	▲			▲								▲									
Nisku	Alberta	1	▲			▲	▲		▲					▲	▲							▲	▲

Mexico

Cárdenas	Tabasco	2	▲			▲	▲		▲					▲									
Poza Rica	Veracruz	2 CNC	▲			▲			▲													▲	▲
Veracruz	Veracruz	4	▲			▲			▲													▲	▲

*API 7-1 Licenced Facility †SCT ‡Licensed to cut AB DWC/H.I.S. TCBC ML Manual Lathe **Canada Contact** +1 780 955 7666

